

## **APPENDIX B**

### **DIGITAL PHOTOGRAPHS**

**(Will be included in final CD deliverable.)**



# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: NW

Photo Name: 2017-09-27\_IMG\_1529.JPG

Date and Time: 9/27/2017 9:47:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Derrick Cobb

Witness: Steve Mason

Caption: Oily sludge/oily impacted soils.





# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: W

Photo Name: 2017-09-27\_IMG\_1530.JPG

Date and Time: 9/27/2017 9:50:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Derrick Cobb

Witness: Steve Mason

Caption: Loading dump truck with oily sludge and oily impacted soils for off-site disposal.





# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: E

Photo Name: 2017-09-28\_IMG\_1534.JPG

Date and Time: 9/28/2017 11:30:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Derrick Cobb

Witness: Steve Mason

Caption: Oily sludge/oily impacted soils.





# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: N

Photo Name: 2017-10-02\_IMG\_1537.JPG

Date and Time: 10/2/2017 8:03:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Derrick Cobb

Witness: Meagan Willis

Caption: Overview of excavation.





# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: NW

Photo Name: 2017-10-03\_IMG\_0523.JPG

Date and Time: 10/3/2017 4:26:00 PM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Meagan Willis

Witness: Steve Mason

Caption: Backfilling of excavation





# Wilcox Oil - Removal Action (Property 006) Photo Report



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: NW

Photo Name: 2017-10-10\_IMG\_0588.JPG

Date and Time: 10/10/2017 4:09:00 PM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Meagan Willis

Witness: Steve Mason

Caption: Completion of compaction and backfilling operations.



Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: SW

Photo Name: 2017-10-11\_IMG\_0596.JPG

Date and Time: 10/11/2017 8:42:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Meagan Willis

Witness: Steve Mason

Caption: Replanting of trees removed during the removal operations.





Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: SE

Photo Name: 2017-10-11\_IMG\_0601.JPG

Date and Time: 10/11/2017 11:12:00 AM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Meagan Willis

Witness: Steve Mason

Caption: Hydro-seeding of the excavated area.





Incident Name: Removal Action (Property 006)

Event Name: Wilcox Oil

Photo Type: Overview

Direction: N

Photo Name: 2017-10-11\_IMG\_0620.JPG

Date and Time: 10/11/2017 5:38:00 PM

Latitude: (b) (6)

Longitude: (b) (6)

Photographer: Meagan Willis

Witness: Steve Mason

Caption: Overview of final restored area.